
## Helical Masonry Repairs – Extensive Repairs to Grange Farm, Darlton, Newark





"I was pleased with the way in which this repair was completed and the fact that it came with a 10 year warranty also pleased my client".

David Perkins

D Perkins Associates

Structural Engineers

Client: Wignall and Sons Ltd

Consultant: D Perkins Associates

Value: £8,400

Project Duration: 1 Week
Completion Date: 2008

6mm bars returned
1.5m around gable
for added stability

Detail RB06

The property at Darlton had suffered settlement to the front right hand corner. With the installation of helical wire we were able to re-distribute the masonry loadings and tie back the effected structure back in to the main body of the property, restoring the buildings structural integrity



Because a mortgage would be required at a later date the repairs were backed up with a 10 year insurance backed structural warranty

