

## Helical Masonry Repairs – Reepham, Lincs



*"All works were carried out to a high standard with little disruption. The operatives were a credit to your company, please pass on my appreciation to them"*

Mrs Swann  
Property Owner

**Client:** Mrs Swann  
**Consultant:** York Sills Consulting Engineers  
**Value:** £2,032.00  
**Project Duration:** 3 Days  
**Completion Date:** 2010

This small structural solutions project involved stabilising the stone gable wall of a 1900's property with minimum disruption to the property owner or her own builders that were in the process of renovating the property

The works involved tying the gable back into the existing property fabric using lateral restraint ties and Heliforce Bars to the corners

